

EXHIBIT 1

Vehicle Name: Ford Escape 4-Dr - Test

Prev

Next

Viewer Options

Damage: Simulated ☒ Show

Xparency: 0.00

Photo View: Front Info...

Filename:

New

Open...

Damage Profile

Impulse No: 1

CDC: 06BDAW3

PDOF (deg)-Azimuth: -177.0

Zenith: 1.3

Width (in): 61.7

Offset (in): -3.3

Number of Zones: 5

Elevation/Dist No: 1 ☒ Is Used

Elevation/Dist (in): 0.0

Crush No	Crush Depth (in)	Free Space (in)	Total Depth (in)
C1	0.0	122.8	122.8
C2	14.8	5.7	20.6
C3	15.6	4.3	19.8
C4	15.6	3.2	18.8
C5	12.5	5.3	17.8
C6	6.9	4.1	11.0

Apply

Reset

Clear

Options...

EXHIBIT

Plaintiff's 1

exhibiticker.com

Rotx Roty

Zoom

27.0 Dolly